Work Order ID 72686 Page 1 Monday, August 08, 2011 1:54:47 PM Item ID: D3537-3 Accept Setup Start **Revision ID:** Stop Item Name: Wearpad Start Otv: 5.00 Start Date: 8/8/2011 **Cust Item ID:** Required Date: 8/9/2011 Rea'd Otv: 5.00 **Customer:** CU-DAR001 Reference: RMA RA111254 Start Run Process Plan: Tooling: Approvals: Date: Date: Stop OC: SPC (Y/N): Date: Date: Reject Sequence ID/ **Operation** Set Up/ Accept Tool ID Tool # Plan Reject Insp. Description Work Center ID Otv Qty Run Hours Code Number Stamp **Revision Nbr** Draw Nbr Rev C D3537 100 0.00 Memo Quality Control INSPECT RA111254 110 0.00 Packaging Sulvelos Memo Packaging RE-IDENTIFY USING NEW B/N 120 QC21- Final Inspection - Work Order Release 0.00

0.00

Memo

QC

Quality Control

N(1-08-9)

Monday, August 08, 2011 1:54:44 PM

Work Order ID: 72686

Parent Item:

D3537-3

Parent Item Name: Wearpad



Start Date: 8/8/2011

Required Date: 8/9/2011

Start Qty: 5.00

Required Qty: 5.00

Comments:

IPP Rev:A

New Issue 07-02-14 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3537-3		Manufactured	No				Each	22.0000		5			

Wearpad

Location		Loc Oty	Loc Code
FP		21	
	70481	21	
FP017		1	
	35697	1	



<u>RA 111254 D3537-3 WEAR</u> <u>PADS</u>

Received @ Dart July 25th, 2011 Inspected August 3rd, 2011

Instructions to put back in to stock

- Parts are D3537-3
- Needs no touchups
- To go back in to stock as is WITH NEW BATCH #

BART Agrospace Ltd

CUSTOMER RETURN

#RA: 1112.54 Date: 11.07.21

Initiator: 3 CLLAN Company: Contact:				Invoice #: SO#: <u>105</u>	<u>105560</u> 331				
Phone No.:			Attach	Copy of E	OHS Return	Authoriza	tion #: <u>61016</u>		
SQ#: NCR	#: <u>11-740</u>	CSR#: _		PAR#: _		_			
Reason for Return:		<u></u>							
Basisine //									
Receiving: // / / / / / / / / / / / / / / / / /	- Freight Comp	pany:	UPST			Prepaid	Collect		
Qty Part#	Batch #	Description			QC				
					Advise	e QA	Date:		
D 3537-3									
	12 70 81	!							
		P							
Condition of Packaging:					Photograph	· ·	yes no		
Paperwork Attached: P/SX	Invoice	·	ARC Do	cs	Other				
QC: Quarantine Location:	<u> Lu mantic</u>	Cor		Sealed /	Accepted /		d / Scrap		
Inspectors Initial:	ate: 1168 13		Photograph Req	juired: ye	es (no)		!		
Oty Part # 25	CHG# Batch # 7158	2 5	Comments Ze Ataik	sheet.		CK 12	oval IIO# Scrap Ia8(c)		
QA Coordinator: Advise GM as to Findings:	Initial:		Date:						
Comments:									
Issue Credit: yes no					Invoice Amount: Less Replacement: Restock Fee: Freight:				
GM Approval:		Date:			Net Credit: DHS		omer		
QA: Enter into Q-Pulse with R					وللأو		NOS US		
Conv. of Customer Return to	stay with work or	dere and an	other convite he f	ilod with h	uctomor cro	4i+	1		